

## 4113 Accessories for 4100 Series DewPoint and Humidity Transmitter

## Model Selection Guide

### Instructions

- Select the desired Key Number. The arrow to the right marks the selection available.
- Make one selection each from Table I using the column below the proper arrow.
- A dot (•) denotes unrestricted availability.

Key Number                      I                      II

\_\_\_\_\_ - \_\_\_\_\_ - \_\_\_\_\_

KEY NUMBER	Selection	Availability				
<b>Accessories for:</b>						
4111 Relative Humidity Transmitter	H411311	↓				
4112 DewPoint & Temperature Transmitter	H411312		↓			
4114 DewPoint & Temperature Transmitter	H411314			↓		
4129 Relative Humidity Transmitter	H411329				↓	
4139 Relative Humidity & Temperature Transmitter	H411339					↓

**TABLE I - ACCESSORY**

Replacement Filter Kit for High Pressure Probe (shield, filter, washer)	40110		•			
Sintered Stainless Steel Filter	40151	•	•	•		
Sintered Stainless Steel Filter with Hydrophobic Coating	40152	•	•	•		
High Pressure Filter	40153		•			
Fluted Shield	40155	•	•	•		
PVC Solar Shield	40156	•	•	•		
Sensor for 4111 RH Transmitter	40173	•				
Sensor for 4112/4114 Transmitters	40194		•	•		
Cooler for Applications 365 - 1000°F for 12" Probe (537,9°C for 304,8 mm)	40196		•	•		
Cooler for Applications 365 - 1000°F for 30" Probe (537,9°C for 762,0 mm)	40197		•	•		
Insertion Removal Device for High Pressure Probe Option	40200		•			
4111 Digital Meter Retrofit Kit	40202	•				
High Cover with Window	40236	•	•			
Short Cover	40237	•				
Pipe/Wall Mount Bracket	40198	•	•			
Digital Indicator for 4129/4139	40728				•	•
Calibration Kit for 4112/4114 (except high pressure)	L0001		•	•		
Calibration Kit for 4111	L0002	•				
Calibration Kit for High Pressure 4112	L0003		•			
Zero Gas Reference Sieve (Dessicant)	L0025		•	•		
Lithium Chloride Calibration Cell (11.3% RH)	L1100	•	•	•	•	•
Potassium Carbonate Calibration Cell (43.2% RH)	L4300	•	•	•	•	•
Sodium Chloride Calibration Cell (75.3% RH)	L7500	•	•	•	•	•

**TABLE II**

No Selection	0	•	•	•	•	•
--------------	---	---	---	---	---	---

Operating Manuals (Order by Part Number)	Part Number
4111 Temperature Compensated Humidity Transmitter	31-41-25-09
4112 DewPoint & Temperature	70-82-25-08
4114 DewPoint & Temperature	31-41-25-10
DewGuard Portable & Temperature Measuring System	31-41-25-11
4129 Relative Humidity Transmitter	31-41-25-13
4139 Relative Humidity & Temperature Transmitter	31-41-25-14