


## H4129R Temperature Compensated Humidity Transmitter With Remote Probe

## Model Selection Guide

- High Accuracy %RH Transmitter
- Remote Probe in 6, 25 or 50' lengths
- One-point field calibration
- NIST Traceable Calibration
- +/- 1% RH Accuracy option



Wall Mount

### Instructions

- Select the desired Key Number. The arrow to the right marks the selection available.
- Make one selection each from Table I through IV using the column below the arrow.
- A dot (•) denotes unrestricted availability.

Key Number      I      II      III      IV  
 [ ] - [ ] - [ ] - [ ] - [ ]

KEY NUMBER	Selection	Availability
Description		
4129R Temperature Compensated RH Transmitter with Remote Probe	H4129R	↓

TABLE I - PROBE LENGTH (in inches)

8 Inch (203,2 mm) Probe	8	•
-------------------------	---	---

TABLE II - PROBE CABLE LENGTH (in feet)

6 Ft. ( 1,83 m) Cable	06	•
25 Ft. ( 7,62 m) Cable	25	•
50 Ft. (15,24 m) Cable	50	•

TABLE III - TEMPERATURE RANGE

No temperature output; must select "0"	0	•
--	---	---

TABLE IV - SPECIAL CALIBRATION OPTIONS

± 1% Accuracy from 0-80% RH, NIST Certificate	X30	•
Standard Accuracy, NIST Certificate	X40	•

See H4113 Accessories (page DPM-9) for Digital Meter and Calibration Items