

## H4129 Temperature Compensated Humidity Transmitter

## Model Selection Guide

- High Accuracy %RH Transmitter
- One-point field calibration
- NIST Traceable Calibration
- +/- 1% RH Accuracy option



Wall Mount

### Instructions

- Select the desired Key Number. The arrow to the right marks the selection available.
- Make one selection each from Table I through III using the column below the arrow.
- A dot (•) denotes unrestricted availability.

Key Number      I      II      III

-  -  -

KEY NUMBER	Selection	Availability
Description		
4129 Temperature Compensated Relative Humidity Transmitter	H4129	↓

TABLE I - HOUSING OPTION

Duct Mount Weather Resistant, 8 Inch (203,2 mm) probe	D9	•
Wall Mount Weather Resistant, 8 Inch (203,2 mm) probe	WM	•

TABLE II - TEMPERATURE OUTPUT

No temperature output - (Must select on 4129)	0	•
---	---	---

TABLE III - SPECIAL CALIBRATION OPTIONS

± 1% Accuracy from 0-80% RH, NIST Certificate	X30	•
Standard Accuracy, NIST Certificate	X40	•

See H4113 Accessories (page DPM-9) for Digital Meter and Calibration Items